

(Witness Cor.)

Renew Sec. Cor. R11W $\frac{512}{513}$ / R10W T205

Fd. orig. 18" Now 26" Fir cor. Tree

with very poor BARK scribe, Now Dead
snag-Leaning Badly. #QB.Ts 25 follows -

orig. 30" Now 60" Fir S. $71\frac{1}{2}^{\circ}$ E. 9² ft,
2 live - shows fair BARK scribe.

orig. 30" Now 64" cedar S. $34\frac{1}{2}^{\circ}$ W. 41⁶ ft,
2 live - shows faint SCAR - we don't open.

orig. 12" Now 16" cedar N. 82° W. 14⁵ ft.

Now 5 ft. hi STUB - Blazes Rotted out NO
scribe fd. - Set Witness Cor. 10 ft.

West of TR4 Cor., 2 1" I.P. & BRASS

Cap MK4 "COUNTY SURVEYOR'S OFFICE

1968 T205 R11W WIT. COR $\frac{512}{513}$ / R10W

10 FT. E. TO COR." & MK. New BT.

40" cedar N. 26° W. 18⁵ ft.

Mkd. "WC T205 R11W 512 CS BT"

64" cedar S. $29\frac{1}{2}^{\circ}$ W. 35⁹ ft.

Mkd. "W.C. T205 R11W 513 CS BT" (OBT.)

This cor. lies on steep Northern
slope approx 100 ft. E. & 150 ft. S.

of creek course N.E. & APPROX.

495 ft N. of C.C. Secs 7 & 18 of 20 & 10

May 13, 1968

URT.
V.P.

~~W. B. T. RAY~~

C. S. File No. 53/66-5 W.B.