

Renew Sec. Cor. R11W  $\frac{513}{524}$  R10W T20S

Fd. UNRECORDED  $1\frac{1}{4}$ " I.P. 2<sup>d</sup> COR. point  
& O.B.T.S 75 follows -

ORIG. 36" NOW 48" FIR S. 81° W. 9<sup>3</sup> ft.  
2 live - shows "T 524" BRASScribe

IN POOR COND. - we REScribe "T20S R11W 524 CS BT"

ORIG. 15" NOW 30" FIR N. 74° W. 8<sup>6</sup> ft.

2 live - shows good SCAR - we do not open.

NO TRACE ORIG COR. TRACE OR OTHER O.B.T.S -

2<sup>d</sup> COR. point in place of I.P. set 1" I.P.

& BRASS CAP MKD. "COUNTY SURVEYOR'S

OFFICE 1968 T20S R11W  $\frac{513}{524}$  R10W"

Reset Old Pipe along side BRASS CAP

& MK. NOW B.T.

15" CEDAR N. 56° W. 15<sup>6</sup> ft.

MKD. "T20S R11W 513 CS BT"

This COR. LIES ON STEEP EAST

SLOPE APPROX 100 FT. ABOVE CREEK

COURSE NORTH. & 99<sup>3</sup> FT. N. 3 $\frac{1}{2}$ ° E. OF

CLOSING COR. OF SEC. 5 18 & 19 OF

T20S R10W.

April 12, 1968

VRT  
J.H.  
W.P.

*[Handwritten signature]*

O.K. J. W. W. B.

427-T20-10

C. S. File No. 53/66-62