

Renew  $\frac{1}{4}$  cor. 56 / 55 T205 R11W  
Fd. unRecorded  $1\frac{1}{4}$ " Steel shaft set  
for cor. with  $4" \times 4"$  white painted  
cedar post & B.T.s as follows -  
orig. 12" now 28" FIR East 5  $\frac{3}{4}$  ft,  
Now Badly decayed - scribe mks visible.  
B.T.s as Recorded in Ren. #30 -  
18" now 24" FIR N. 33° W. 12  $\frac{3}{4}$  ft,  
Now 20 ft. high snag - shows scar  
16" now 26" FIR S. 12  $\frac{1}{2}$ ° E. 16  $\frac{3}{4}$  ft  
Now stump - shows scar - also a stump  
N. 75° W. 8  $\frac{1}{2}$  ft. - but is not a B.T. -  
we do not set BRASS CAP -  
MARK. new B.T.s -

9" Alder N. 45° W. 16° ft  
Mkd. " $\frac{1}{4}$  56 CS BT" (on bark)  
8" Alder S. 26° W. 13  $\frac{3}{4}$  ft,  
Mkd. " $\frac{1}{4}$  56 CS BT" (in wood)  
7" Alder S. 70° E. 11  $\frac{1}{2}$  ft,  
Mkd. " $\frac{1}{4}$  55 CS BT" (in wood)  
5" Alder N. 34° E. 14  $\frac{1}{2}$  ft,  
Mkd. " $\frac{1}{4}$  55 CS BT" (on bark)

Feb 25, 1970

A/R Tracy

#85

VRT  
J.A.H.  
VOR

O.V.  
J.W.M.

G. S. File No. 53/66-93