

Revised

30/29
31/32

Tails R9W

Found

42" D.F. Fir diam 50' N17E 58'

Shows Scar

1" Cedar diam 7' S84W 42'

Tails R9W 531

32" D.F. Fir diam 10' N19W 15'

Shows old Scar -

Also Brass cap MID.

B L M
Tails R9W

530/529

531/532

1967

OK
D.W.B.

New Bearing Tree

12" Cedar S14½ E 51'

Scinded Tails R9W 537 CS BT

21" cedar N39W 26'

Scinded Tails R9W 530 CS BT

9-30-7

J.M.S.
Tails
R9W

Note Area to the South has
been logged.

C. S. File No. 53/66-123

DIETZGEN NO. 385-6

11
20