

Renew Sec. Corner

T 205

32 | 33 ESW

5 | 4

T 215

Found:

Original 8" D Fir (now 20")

S 71W 42.9 ft.

Tree has been previously opened, scribing visible ("W" and other marks)

No trace of other trees

(there is a large fir in the NE Quadrant with a BLM tag. Tree doesn't fit bearing. We cut open this tree but found nothing.

Set Brass Cap at Cor.

Marked:

Doug. County Surv. Office.

T 205

532 | 533 E

55 | 54 W

T 215

FILED

RECEIVED

JUN 14 1965

(over)

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 53/101¹

DIETZGEN NO. 385-6

New Bearing Trees:

5" D. Fir N 12W 96 ft.
Marked:

T205 R5W S32 CSBT

12" Hemlock N63E 31 1/2
Marked:

T205 R5W S33 CSBT

8" Hemlock S50E 22 1/2
Marked:

T215 R5W S4 CSBT

June 10, 1965

BR

M.S.

Corner Fd OK:

1/4 Corner between
sec 1, T215, R6W &
sec 6, T215, R5W

Fd. Cor as described in
Ren. # 49, plus two
BLM Bearing Trees