

4 Renew 1/4 Cor 19/20  
T225 R 5W

Found:

18" Maple Scribing Vis.  
N68 1/2 E 64°

24" R Fir (Now Snag)  
N44 W 59°

CSO Brass Cap at cor.  
1958 Renewal #52

New Bearing Tree:

21" D Fir S19W 93°

Marked 1/4 S19 CSBT

Feb 9, 1965

BR

WS

MS

+ \* 109 ✓