

10  
Renew Section Cor.

14 | 13 T225  
23 | 24 R5W

Found corner as described  
by MEGILICUDDY (Ren. #26)  
Burnt stumps fit good  
for bearing & distance and  
appear to have been  
about the right size.

3/4" iron pipe in 4 way  
fence.

Mc Gillicuddy didn't scribe  
any trees.

New Bearing Trees

12" D. Fir S43E 180 ft.  
Marked T225 R5W S24  
CS BT

10" D. Fir N32W 180 ft.  
Marked T225 R5W S14  
CS BT

13" D. Fir S25W 33.1 ft.  
Marked T225 R5W S23  
CS BT

QX 116

July 1, 1965  
C. S. File No. 53/101<sup>39</sup> BR - WS - MS.

DIETZGEN NO. 385-6