

Renew $\frac{1}{4}$ Cor. 10/11
TZZS R. 4W

Found: 48"
40" Fir (now stump)
2^o SIDE Original BT
Shows Bark scribing
original stone
has been disturbed
No trace of S.W. Tree

Set brass cap at Cor.

Marked:

County Surveyors Off.

TZZS

$\frac{1}{4}$ S | S
10 | 11

R 4W

1965

Jan 20, 1965
BR
W/S
MS

New Bearing Trees:

18" Cedar S 31 E 29^o

Marked $\frac{1}{4}$ S 11 CS BT

14" Cedar S 61 W 26^o

Marked $\frac{1}{4}$ S 10 CS BT

✓
#107
+ X

U. S. File No. 53/101.78