

Renew W. $\frac{1}{4}$ / 511 T215 R10W

Ed. 1" I.P. filled with concrete at cor.
point - BRASS cap Broken off & gone
+ C.B.T. -

Orig. 36" Now 46" Hemlock S. 70° E. 31 $\frac{1}{2}$ ft.

alive - shows good scar - we do not open
we rescribe - " $\frac{1}{4}$ 511 C S B T" N.E. B.T.

gone - call on creek to north fits

good - set at cor. point MKD^{S.O.} COUNTY

SURVEYOR'S OFFICE 1968 T215

$\frac{1}{4}$ / 511 R10W " & MK. New B.T. -

14" Hemlock N. 89° E. 62 $\frac{1}{2}$ ft.

MKD. " $\frac{1}{4}$ 511 C S B T" - Deposit
old pipe along side new monument.

This cor. lies on very steep
northerly slope 46 ft. S. of creek.

The call dist bet $\frac{1}{4}$ 510 & $\frac{1}{4}$ 511 fits good.

March 13, 1968

VRT

J.H.

V.R.

A/R Tracey

44

J.O.K. J.W.B.

C. S. File No. 54/1-14