

Renew $\frac{1}{4}$ COR. 533 | 534 T215 R10W

Fd. Remains of old concrete filled I.P.
with 1919 GLO BRASS CAP Lying along side
& O.B.T.s as follows -

Orig. 14" "Now 16" FIR East 13 ft.

Now 529 - we opened & find " $\frac{1}{4}$ 534 BT"

scribe & Reverse -

Orig. 14" "Now 22" FIR S. 53° W. 13 ft.

21.00 - shows good scar - we Rescribe above

old scar " $\frac{1}{4}$ 533 CS BT" - at cor. point

in place of old I.P., set 1" I.P. & BRASS CAP

Mkd. "COUNTY SURVEYORS OFFICE

1970 T215 $\frac{1}{4}$ 533 | 534 R10W" Deposit

old cor. material along side - MARK

New BT -

24" D. FIR N, 65° E. 8 ft.

Mkd. " $\frac{1}{4}$ 534 CS BT"

This cor. lies on very steep

N.E. slope in very dense

Rhododendron brush.

Feb. 1970

V.R.T.
J.G.H.
V.P.P.

~~J.R. Tray~~

J.W.B.

#36

C.S. File No. 54/1-21