

12/31

Renew Sec. Cor 52 | 51 T225 R10W

Fd. 1963 CAD. BRASS CAP & B.T.'s

as follows -

1963 26" Sawn FIR STUMP S. 51 1/2° W. 25 1/2 ft.

scribe visible. - 1919 B.T.'s

Down 1919 BRASS CAP gone.

Set 6 ft. Steel Fence Post

along Side BRASS CAP & MK new

B.T.s -

18" Alder S. 72° E. 41° ft.

Mkd. T225 R10W S1 C5 BT"

16" Alder S. 51° E. 36 1/2 ft.

Mkd. T225 R10W S1 C5 BT"

This cor. lies on very steep

N.W. slope near N.E. cor. of


clearcut unit & approx. 100 ft.

west & 75 ft. south of solid

Rock Ravine course N.W.

May 23, 1968

U. RITT  
D.P.



#18'  
#43 T22-10

C.S. File No. 54/1-31