

Review Closing Township Cor. T205 R12W | ⁵³¹56 R11W

Fd. o. B.T.s as follows -

ORIG. 40" Now 22" FIR N. 6° E. 21 1/2 ft.
Now STump & shows S R 11W S ON opened
Blaze - probably 14" when MKd - Ring
COUNT 60 + YEARS -

ORIG. 40" Now 48" FIR N. 43° W. 20 1/2 ft.
Now Tipped out STump - Lying face Down.
NO TRICE of S.E. B.T. - Set 1"
I.P. & BRASS CAP MKd. "COUNTY
SURVEYOR'S OFFICE 1967 T205
R12W CC. | ⁵³¹56 R11W T215" & MK.
New B.T. -

30" D. FIR STump S. 20° E. 6 3/4 ft.
MKd " T215 R11W 56 CC CS BT"
No other stumps OR Trees close.
This cor. Lies on very steep
N.E. slope approx 195 ft S,
of Township cor of T20 & 215 R12W
NOTE: BRASS CAP is set ON East side
& under 30" Log.

March 30, 1967

V.R.T.
J.H.
D.W.

~~18-T21-12~~
~~15-T20-11~~
~~14-T20-12~~
~~13-T20-11W~~
RAW

S.S. File No. 54/1-33

X