

Renew 1/4 Cor.

532 T255 E3W

55 T265 E3W

Found:

Original 16" B. Oak S11E90LK
(Now Low cut stump)

Original 12" W Oak North 32LK
(Now Fallen snag)

15" Fir (1943 Resurvey)

N83 1/2 E 24 LK.

(Now stump scribing vis.)

13" Fir (1943 Resurvey)

S22 1/2 E 19 LK.

(Now stump scribing vis.)

Brass Cap at Cor. (GLD1943)

New Bearing Trees:

11" Oak S63W 23⁶ ft.

Marked: 1/4 55 CS BT

7" Oak N45W 29⁶

Marked: 1/4 532 CS BT

July 15, 1965

BR

WS

MS No. 54/7-1