

Renew 1/4 Cor.

S 31 | 32 T 25 S R 3 W

Found:

11" Fir (now stump)

S 11 E 63 LK.

Shows Good scribing

1/4 S

18" Fir (now Burnt Stp) S 4 W 10 LK.

Shows scribing 1/4

Brass Cap at corner

(GLO 1943)

New Bearing Trees:

12" Oak S 24 E 25 3

Marked:

1/4 S 32 CS BT

5" Oak S 61 W 28 3

Marked:

1/4 S 31 CS BT

July 15, 1965

BR

WS

MS

+ * 335
⊙

File No. 54/7-2