

Renew $\frac{1}{4}$ COR. 54 $\frac{1}{2}$ 53 T265 R3W

Fd. ORIG BT 85 follows -

18" Now 21" B. OAK (stump) S. 14° W. 310 $\frac{1}{2}$ Ft.

we chop out "BT" scribe & Reverse from
Back side. NO BT East of Line MKd.

Originally. Set 1" I.P. & BRASS Cap at

COR. PT. MKd. COUNTY SURVEYOR'S OFFICE

1966 T265 $\frac{1}{4}$ 54 $\frac{1}{2}$ 53 R3W" & MK

New BTs -

27" Redcedar S. 22° W. 38 $\frac{1}{2}$ Ft.

Mkd. $\frac{1}{4}$ 54 CS BT"

20" Red Cedar S. 42° E. 21 $\frac{1}{2}$ Ft.

Mkd. $\frac{1}{4}$ 53 CS BT"

This COR lies on Steep S. Slope

Jan. 20, 1965

J.W.B.
V.R.T.
J.L.

+ X #134

C.S. File No. 54/7-11