

Renew Most East. S.E. COR. DLC. 45 T26S R3W

Fd. The following BT's for a cor. -

ORIG. 6" Now 11" W. oak N. 40° W. 15 3/4 ft

We open & find. " 5 BT" scribe & Reverse.

ORIG. 8" Now 8" B. oak S. 80° W. 13 3/4 ft,

DOWN-Dead & Rotten No scribe Fd.

We set 1" I.P. & BRASS Cap MKd "COUNTY

SURVEYORS OFFICE 1966 T26S

E.S.E. COR. DLC 45 - R3W"

A MK. New BT's -

12" W. oak S. 8° W. 5 7/8 ft,

Mkd. " E.S.E. DLC 45 CS BT"

12" D. FIR. S. 67° E. 23 1/2 ft,

Mkd. " ESE DLC 45 CS BT"

This cor. lies approx. 250 ft.

East of INT. L. COR of DLC 45.

Feb 14, 1966

V.R.T.
M.S.
J.H.

[Handwritten signature]

FILED
RECEIVED

FEB 14 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#14
#0

U.S. File No. 54/7-25