

Renew Sec. Cor. ^{531 532 T255} 56/55 T265 R3W

Fd. 1943 GLO BRASS CAP MKD " T255 R3W

531/532
56/55 T265 1943 " & STUMPS of following

BTS -

ORIG. 40" FIR (STUMP) S. 60° W. 4 1/2 FT.

FRAGMENTARY BARK SCRIBE VISIBLE.

60" FIR (STUMP) N. 12 3/4° E. 42 3/4 FT.

SCRIBE & REVERSE VISIBLE.

20" FIR (STUMP) S. 58 1/2° E. 43 1/2 FT.

BURNED. " S " SCRIBE VISIBLE ON FACE.

22" FIR (STUMP) N. 66 1/2° W. 42 3/4 FT.

BADLY BURNED. FRAGMENTARY SCRIBE VISIBLE.

WE MK. NEW BTS -

7" D. FIR N. 23 1/2° E. 50 3/4 FT.

MKD. " T255 R3W 532 CS BT "

15" D. FIR N. 49° W. 130 1/4 FT.

MKD. " T255 R3W 531 CS BT "

NO TREES AVAILABLE TO SE. OR SW.

BRASS CAP LIES AT FENCE COR. COURSE

E.-W. & S.

Feb. 18, 1966

V.P.T.
M.S.
J.H.

(Handwritten signature)

* #41-726
#162-726

C. S. File No. 54/7-42