

Renew $\frac{1}{4}$ $\frac{51}{512}$ T265 R3W

Fd. B.T.s 2 live & in good condition
as Recorded in Ren. # 76 by J.W.B.
in 1957. At the point for cor.

No trace of C.S. Brass cap fd.

Due to addition of Riprap to hold
fill of N. unpaved Hiway. - Set

1" I.P. & Brass cap MKD. " COUNTY

SURVEYOR'S OFFICE 1972

$\frac{1}{4}$ $\frac{51}{512}$ T265 R3W " Note: hole

could only be dug 1 ft. deep -

Built Rock mound 3 ft across

& 2 ft. high around pipe.

This cor lies 140 ft. west

of west edge pavement &

across Road from Rock Creek

Guard Station.

3-15-72

VIR.T. - LEM.

V. B. Tray

#193

C. S. File No. 54/7-169