

Renew $\frac{1}{4}$ S 35 only T235 R8W
T245

Fd. B.T.s as follows —

orig. 40" Now 46" Fir N. 71° W. 92 ft

Now Badly decayed 50% — we open
& find $\frac{1}{4}$ S " Scribe orig. S.W.

B.T. Down & Rolled out of Place.

Set 1" I.P. & Brass cap MKd. COUNTY

SURVEYOR'S OFFICE 1967 T235

$\frac{1}{4}$ S35 T245 R8W " & MK. New

B.T.s —

11" Hemlock N 38 $\frac{1}{2}$ ° W, 21 $\frac{1}{2}$ ft,

Mkd. " $\frac{1}{4}$ S 35 CS BT "

15" D. Fir N. 30° E. 21 $\frac{1}{2}$ ft,

Mkd. " $\frac{1}{4}$ S 35 CS BT "

This cor. lies on Gentle Northerly
slope of spur ridge approx
215° ft. East of $\frac{1}{4}$ S 2 of 24-8

Feb. 16, 1967

URT
J.H.
D.W.

FILED
RECEIVED

(Handwritten signature)

FEB 16 1967

#54-T24-

#74

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

*O.K. J.W.B.

C. S. File No. 54/12-13