

Renew $\frac{1}{4}$ 532 T235 R8W
T245

Ed. 1963 c3d BRASS properly MKd. & $\frac{1}{2}$ "
ALUMINUM Pipe along side, & B.T.s as follows -
Orig. 60" Hemlock N. 29° W. 11 $\frac{3}{4}$ ft.

Now Turned out 5 Temp - Nearly facedown
No Trace other orig. B.T. -

1963 40" Hemlock N. 36° W. 51 $\frac{5}{8}$ ft.
2 live - face Burned - we Rescribe.

" $\frac{1}{4}$ 532 cs BT"

1963 6" Hemlock N. 53 $\frac{1}{2}$ ° W. 81 $\frac{3}{4}$ ft.

Down & Dead. - face Burned.

MK. new B.T. -

5" Hemlock N. 36° W. 41 $\frac{5}{8}$ ft.

MKd. " $\frac{1}{4}$ 532 cs BT"

This cor. lies approx. 150 ft West
of small creek course N.

Jan 21, 1967

V.R.T.
J.H.
D.W.

FILED
RECEIVED

JAN 20 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

* #60 ✓ o.n. J.W.D.

C. S. File No.

54/12-2