

Renew Sec. Cor. 533 | 534 T235 R8W
T245

Fd. B.T.'s as follows -

ORIG. 60" Now 62" FIR N. 83° E. 19' ft.

2 live - shows "T W" & fragmentary
BARK scribe.

ORIG. 40" Now 43" FIR S. 67° W. 40' ft.

2 live - shows good SCOR. - do NOT open

ORIG. 12" Now approx 16" FIR N. 79° W. 41' ft.

Now decayed Remains of stump - find "BT"

scribe set 1" I.P. & BRASS COP

Mkd. "COUNTY SURVEYORS OFFICE

1967 T235 533 | 534 R8W T245" &

MARK New B.T.s -

16" D. FIR N. 34 1/2° E. 22' ft.

Mkd. "T235 R8W 534 CS BT"

12" D. FIR N. 37° W. 25' ft.

Mkd. "T235 R8W 533 CS BT"

This COR. lies on steep S. slope
approx 40 ft. west of shallow draw
course S.W.

FILED

RECEIVED

Jan, 6, 1967

JAN 18 1967

#45
#55
#60
XO
R. J. [Signature]

J.H.
D.W.
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

C. S. File No. 54-12523