

Renew Sec. Cor. <sup>518 | 517</sup> 519 | 520 T235 R8W

Fd. 4" squared Post & following BTs -  
Orig. 24" Now 26" Hemlock N. 4° E. 8<sup>6</sup> ft.  
Turned out & Laying face Down.

Orig. 18" Now 28" Hemlock S. 76° E. 14<sup>5</sup> ft.  
open - face badly Rotted.

Orig. 16" Now 24" Maple S. 13° W. 29° ft.  
Shows good SCAR - we do not open.

Orig. 24" Now 31" Hemlock N. 22° W. 31<sup>2</sup> ft.  
open & shows "S18 W" scribe - This  
BT burned at base. We set 1" I.P.  
& Brass cap MKd. "COUNTY SURVEYOR'S  
OFFICE 1965 T235 <sup>518 | 517</sup> 519 | 520 R8W"

& MARK following BTs -

15" Hemlock N. 25° W. 33° ft. (New BT)  
MKd. "T235 R8W S18 CS BT"

20" cedar N. 81° E. 11<sup>5</sup> ft. (New BT)  
MKd. "T235 R8W S17 CS BT"

28" Hemlock S. 76° E. 14<sup>5</sup> ft. (old BT)  
MKd. "T235 R8W S20 CS BT"

This cor. Lies in bottom of small  
ravine course South.

June 24, 1965

V.R.T.  
T.C.

~~V.R.T.~~  
+X

C.S. File No. 54/12-33