

Renew Sec. Cor. $\frac{55}{58} \frac{54}{59}$ T235 R8W

Fd. one Live BT. as follows -

Orig. 24" Now 40" Fir N. 67° W. 25 $\frac{1}{2}$ ft.

We open & find " 55" scribe. all

other ~~orig~~ B.T.s now only Badly Decayed

Remains of 5 Stumps, apparently

destroyed by old fire. Set 1"

I.P. & Brass Cap MKd. "COUNTY

SURVEYOR'S OFFICE 1966 T235

$\frac{55}{58} \frac{54}{59}$ R8W" - set in mound of stone.

MARK. New B.T.s -

13" D. Fir S. 21° W. 23 $\frac{0}{10}$ ft.

Mkd. " T235 R8W 58 CS BT "

12" D. Fir S. 18° E. 15 $\frac{4}{10}$ ft.

Mkd. " T235 R8W 59 CS BT "

8" D. Fir. N. 64° E. 5 $\frac{7}{10}$ ft.

Mkd. " T235 R8W 54 CS BT "

5" D. Fir N. 28° W. 8 $\frac{8}{10}$ ft.

Mkd. " 55 CS BT "

This Cor. Lie 6 ft. East of

Top of Ridge Sloping N.

FILED

RECEIVED

V.R.T.

Dec. 23, 1966

DEC 23 1966
dlw.

[Handwritten signature]

COUNTY SURVEYOR

O. G. S. REG. No. 354 / 12-1 DOUGLAS COUNTY, ORE