

Review Sec. Cor. <sup>520/521</sup> 529/528 T235 R8W

Fd. one B.T.s follows -

Orig. 60" Now 76" EIR N. 76° W, 45 5/8 ft.  
we open & find "B" scribe & Reverse  
face apparently Burned Before Blaze  
healed over. No Trace other Orig.

B.T.s - Set 1" I.P. & BRASS CAP MKD  
"COUNTY SURVEYOR'S OFFICE 1966  
<sup>520/521</sup>  
T235 529/528 R8W" & MK. New B.T.s -  
16" Hemlock N. 79° W, 13 3/4 ft.

Mkd. "T235 R8W S 20 CS BT"

12" Hemlock S. 31 1/2° W, 24 1/2 ft.

Mkd. "T235 R8W S 29 CS BT"

9" Hemlock S. 25° E, 19 0 ft.

Mkd. "T235 R8W S 28 CS BT"

16" Hemlock N. 54° E, 26 3/4 ft.

Mkd. "T235 R8W S 21 CS BT"

This cor. Lies on top of  
small SPUR sloping To N.W.  
in Heavy Timber.

FILED

RECEIVED

Dec. 7, 1966

VRT  
DEC 7 1966  
D.W.

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

XO#45

O.K. J. W. C. S. File No. 51/12-53