

Renew  $\frac{1}{4}$   $\frac{510}{515}$  T235 R&W

Fd. Q.B.T.s as follows -

orig. 24" now 48" cedar S. 5° W. 16 $\frac{1}{2}$  ft.

alive - Badly injured on west side

" $\frac{1}{4}$ " scribe visible on badly decayed blaze -

orig. 40" now 54" Fir N. 5° W. 28 $\frac{1}{2}$  ft

(slope) alive - shows " $\frac{1}{4}$  5" bark scribe in poor cond. & RT scar. Set

1" I.P. & BRASS cap MKd. "COUNTY SURVEYOR'S OFFICE 1967

T235  $\frac{1}{4}$   $\frac{510}{515}$  R&W" & MK. New B.T.s

12" Hemlock N. 61° W. 27 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  5 10 CS BT "

14" Hemlock S. 49° W. 15 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  5 15 CS BT "

COR. Lies on moderate changing to steep N.E. slope approx 100 ft. west of creek course N.E.

**FILED  
RECEIVED**

March 7, 1967

V.R.T.  
MAR 7 1967  
D.W.

*[Handwritten signature]*

**COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.**

D.K. J.C. S.F. No. 54/12-62