

Renew Sec. Cor. $\frac{534}{53}$ | $\frac{535}{52}$ T205 Lane
7215 R5W Doug. Co.

Fd Three Bts as Follows -

Orig. 16" Now 22" Fir N. 59° E. 16⁵ ft.

Probable 10²⁵ error in distance should be 23⁵ ft.

Shows "T205 R5 S35" scribe - 6° ft hi. Stump.

Orig. 30" Now 44" Fir S. 15° E. 35⁶ ft.

Shows "215 5W 52" Bark scribe, alive.

Orig. 12" Now 25" cedar S. 30° W. 21⁸ ft.

open face Rotted - No scribe, alive, No

Trace N.W. B.T. - Set 1" IP & Brass

Cap MKd. "Doug. Co. SURVEYOR'S OFFICE

1965 T205 R5W $\frac{534}{53}$ | $\frac{535}{52}$ T215" & MK.

New Bts -

6" Hemlock S. 87° W. 23³ ft.

Mkd. "S 3 DCS BT"

7" D. Fir S. 77° E. 21⁴ ft.

Mkd. "T215 R5W 52 DCS BT"

No Trees available to North.

July 22, 1965

V.R.T.
M.D.
M.S.
T.C.

FILED
RECEIVED

JUL 22 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 54/14-2

[Handwritten signature]
#15
+ ✂