

Renew  $\frac{1}{4}$   $\frac{516}{521}$  T21 S R5W

Ed. Badly Burned cedar BT 25  
follows -

ORIG. 9" Now approx. 12" cedar S. 11° W. 16<sup>5</sup> ft.

fd. "BT." Reverse scribe & partial face  
of upper scar. No trace of other

orig. BT. we set 1" I.P. &

BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1965 T21 S  $\frac{516}{521}$  R5W"

& MK. New BT's -

18" D. FIR S. 19° W. 38<sup>5</sup> ft.

Mkd. " $\frac{1}{4}$  S 21 CS BT"

20" D. FIR N. 78° E. 96° ft.

Mkd. " $\frac{1}{4}$  S 16 CS BT"

This cor lies on west side  
of top of spur Ridge running SW.

August 19, 1965

VRT

M.D.

M.S.

T.C.

FILED

RECEIVED

AUG 19 1965

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

#128<sup>v</sup>

+X

C. S. File No.

57/14-6