

Renew Sec. Cor R5W $\frac{513}{524}$ | $\frac{518}{519}$ R4W T21S
Fd. $\frac{3}{4}$ " I.P. - Bent over & B.T.s as recorded
in Ren # 87 as follows -

27" D. FIR S $32\frac{1}{2}^{\circ}$ E. 37 $\frac{1}{2}$ ft.
alive - scribe visible on pitched blaze.

12" D. FIR N. $69\frac{1}{2}^{\circ}$ W. 133 $\frac{2}{3}$ ft.
alive - scribe visible on pitched &
healing blaze. O.B.T. to S.E. alive.

& O.B.T. stump NW. in place & shows
scribe - 2^d cor. point in place of
I.P. set 1" I.P. & BRASS COP MKD. -

"COUNTY SURVEYOR'S OFFICE
1968 T21S R5W $\frac{513}{524}$ | $\frac{518}{519}$ R4W" &
MK. new B.T. -

6" D. FIR N. $1\frac{1}{2}^{\circ}$ E. 34' ft.
MKD. "T21S R4W S18 CS BT"

This cor. lies 1 ft. south of
E-W fence. No trees available
to S.W. Reset old I.P. along
side BRASS COP.

Dec. 31, 1968

URT
FWT,
V.P.

J. P. Tracy

#102-7214

#134-7215

G.S. File No. 5214-44