

Renew $\frac{1}{4}$ 513 + 518 T235

Fd. Brass Cap Recorded in Renewal #37
Pushed out of place. Orig. 50" Fir
Snag. still in place. Renewal BT's 25

Follows -

16" cedar S. $13\frac{1}{2}^{\circ}$ E. 99' ft

Now Snag. 10' ft High - scribe visible

14" D. Fir N. 35° W 12' ft. (alive)

in fence cor. face almost healed over
scribed high because of fence wire.

We Reset BR 255" cap & MARK New BT-

9" D. Fir N. 18° E. 31' ft.

Mkd. $\frac{1}{4}$ 518 CS BT"

Oct. 25, 1965

VRT.
M.S.
J.L.

23-5: 78 ✓

110 ✓

+ *