

R4W 1 6 R3W

Renew Sec. Cor. 12/7 T235 R's 3 & 4w

Fd. 2" x 2" square Post & BT's as follows

Orig. 8" ? Now 60" Fir N. 32° W, 31° Ft.

Shows old fragmentary BARK scribe.

Orig. 20" Now 24" cedar S. 28° E. 26 1/2 ft.

Down & out of Place - we do not open.

Orig 8" Now 20" cedar S. 35° W, 35° Ft.

Down Find Reverse Scribe" 512 T23 BT"

Previously Removed FROM BT. No

Trace N.E. B.T. - we set 1" I.P.

& BRASS Cap MKD. "DOUG. CO. SURVEYORS

OFFICE 1965 T235 R4W 512/56 51/57

R3W " & MK New BT's -

12" D. Fir S. 9° W, 10 2/3 Ft.

Mkd. " T235 R4W 512 DCS BT "

9" D. Fir S. 60° E. 60° Ft.

Mkd. " T235 R3W 57 DCS. BT "

16" D. Fir N. 28° E, 23 3/4 Ft.

Mkd. " T235 R3W 56 DCS. BT "

NO TRACE close TO N.W. - This

Cor. on Lane - Douglas Co. Line.

Nov. 3, 1965

V.R.T.
M.S.

10-23-3

125

+*

G.S. File No. 54/16-20