

Renew $\frac{1}{4}$ $\frac{513}{524}$ T235 R4W

Fd. The following BT's at cor. -

Orig. 14" Now 24" Fir (SNDG) N. 55° E. 15⁸ ft.

upper face gone - we open lower section find

"BT" scribe. SW. Orig. BT Now hole

in ground. with rotting wood lying around.

Weyerhaeuser's BT. Now STUMP & TURNED

OUT. - C.S. 53/108

36" D. FIR N. 4° W. 13° ft.

Shows $\frac{1}{4}$ 513 BT 363" BARK scribe.

We set 1" I.P. & BRASS CAP MKD. COUNTY

SURVEYOR'S OFFICE 1965 T235

$\frac{1}{4}$ $\frac{513}{524}$ R4W " & MK. NEW BTs -

21" D. FIR S. 51° E. 51⁹ ft.

Mkd. $\frac{1}{4}$ 524 CS BT"

30" D. FIR N. 21° E. 27⁸ ft.

Mkd. $\frac{1}{4}$ 513 CS BT"

Nov. 30, 1965

U.R.T.
M.S.
J.L.

FILED
RECEIVED

NOV 30 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 54/16-28

$\frac{513}{524}$
+ X