

Renew $\frac{1}{4}$ 523/524 T235 R4W

Fd. Haines "T" IRON at cor. pt. - Not

Recorded. - BT's 25 follows -

orig. 48" Now 50" FIR (STUMP) N. 60° E. 14 $\frac{5}{8}$ ft.
NO SCAR - NO SCRIBE fd. - (face)

orig. 18" Now 36" FIR S. 87° W. 46 $\frac{3}{8}$ ft (face)

$\frac{1}{4}$ " BARK SCRIBE very old in poor cond.

"363 $\frac{1}{4}$ 523 BT" Rescribe above old.

BT alive & in good cond.

also - 8" Hemlock N. 37° E. 4 $\frac{8}{16}$ ft.

UNRECORD MKD. " $\frac{1}{4}$ 524 BT" & Haines

Button on face - LEARNING badly & LIFTING
out of ground. we MARK new BT's -

6" Yew N. 21° W 34 $\frac{6}{16}$ ft.

MKD. " $\frac{1}{4}$ 523 CS BT"

10" Hemlock N. 52° E. 14 $\frac{7}{16}$ ft.

MKD. " $\frac{1}{4}$ 524 CS BT"

NOV. 24, 1965

V.R.T.
M.S.
J.L.

~~FILED~~
RECEIVED

NOV 24 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.
C. S. File No. 54/16-30

F X