

Renew $\frac{1}{4}$ 533 / 534 T235 R4W

Fd. BT's Recorded in Ren. #47 - Haines

"T" IRON has been pushed out & cedar

STAMP used for orig BT. also gone.

To Reestablish Haines COR, we set

1" I.P. & BRASS Cap at COR. MKd. "COUNTY

SURVEYOR'S OFFICE 1965 T235 $\frac{1}{4}$ 533 / 534

R4W" set FROM Haines BT's as follows-

5" NOW 7" W. F. R. S. $40\frac{1}{2}^{\circ}$ E. 79.5 FT.

Healed Blaze - we do NOT open.

7" NOW 11" R. Cedar N. $72\frac{1}{2}^{\circ}$ W. 126.5 FT.

scribe visible on partially healed blaze.

This COR. Lies on E. Edge of Road

COURSE N. & S CURVING to S.W.

Nov. 12, 1965

V.R.T.
M.S.
J.L.

V.R.T. Tracy

FILED
RECEIVED

NOV 12 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 54/16-36

4130

+X