

522 | 523  
Renew Sec. Cor. 527 | 526 T235 R4W

Ed. Haines' T "Iron & 3/4" I.P. 2<sup>+</sup> cor.  
point. See CS. file <sup>Rem. #142</sup> 54/16 Haines field

~~Book Pages 18 & 19 & B.T.s 25 follows -~~

ORIG. 60" Now 64" FIR S, 25° E, 60<sup>2</sup> ft.

REBARK SCRIBED "363 T235 R4W 526 BT"

Now SN29.

Haines BT-14 "Now 20" D. FIR N, 60° W. 50° ft.

BARK SCRIBED, "363 T235 R4W 522 BT" with

Haines Button on face, 2 live.

Haines BT-36 "FIR S, 89° W. 44<sup>±</sup> ft.

Now STAMP - BARK SCRIBE "3 BT" NO TRACE ANY

OTHER B.T.s - we do not set BRASS CAP. - MK IN NEW B.T.s

8" Hemlock N, 35° W, 22<sup>±</sup> ft.

Mkd. "T235 R4W 522 CS BT"

14" Hemlock N, 14° E, 44<sup>1</sup> ft.

Mkd. "T235 R4W 523 CS BT"

9" Hemlock S, 62° E, 63<sup>2</sup> ft.

Mkd. "T235 R4W 526 CS BT"

NO TREES AVAILABLE TO SW. COR.

LIES IN CORNER OF CUTOFF UNIT IN

Sec. 27.

Sept 26, 1966

V.R.T.

J.H.

#142  
\* *B. Gray*

C. S. File No. 54/16-45