

Renewal SB/59 T315 R4W

Found

36" D Fir Now 36" S47E 17E
Shows good Scar.

30" D Fir, Now STUMP, N152E W 10E
Shows Scar

Cor. Tree 24" Fir Now 24"
Scribe visible $\frac{1}{4}$ S ON W FACE

All C.B.T's

Renewal:

Set Brass cap at $\frac{1}{4}$ cor NW20
County Surveyors Office

T315 R4W

$\frac{1}{4}$ SB/59

1966

New Bearing Tree

10" D Fir N12E $\frac{1}{4}$ T

Scribed as CS BT

3-15-66
[Handwritten signature]

Renewal #25

① #139

O.K. J.B.

C.S. File No 54/20-5

DIETZGEN NO. 388-6