

Renewal S33/S34 T3/SRAW

Found

40" Fir Now snag N60W 52'  
Free badly burnt but some  
scribe marks still visible.

14" Fir S6E 54'  
No trace of this tree

No trace of Iron P.P.

Renewal:

Set Brass cap at  $\frac{1}{4}$  cor MKD.

County Surveyors office

T3/SRAW

S33/S34

1966

Next Bearing Trees

17" Fir S42W 33'  
Scribed  $\frac{1}{4}$  S33 CS BT

8" Fir N37E 67'  
scribed  $\frac{1}{4}$  S34 CS BT

This cor falls in skid Rd.

2-16-66

*[Handwritten signature]*

Renewal #16

O.K. J.W.B.  
DIETZEN NO. 385-6

X #109

C. S. File No. 54/20-9