

Renewal 528/527 T315R4W

Found

Iron Pipe
6.3 FT W.O. N 34 1/2 W 108 E
good condition scribe visible

14" Ash N 85° 20' E 177 E
scribe visible "4.5 FT"

creek bank badly washed
probably lost this tree

Iron Pipe as noted 8"
under ground.

New Bearing Tree + object

D. Fir S 69 E 508 S
scribed #527 CS PT

Power Pole #E1570 West 20 E

Renewal #39

2-17-66

JMO
JOS
JMO

#110