

Renewal

522/523
527/526

T315 R4W

Found:

Iron Rod at Sec cor

8" Fir New Rod. S19W 29°

Scribe visible "27 CS"

I find this distance 70 ft - 32°

16" D. Fir New 18" S18E 17°

Stands good Sours

Renewed.

Along Side I. Rod.

Set Brass cap at Sec cor NW

county Surveyors office

T315 R4W

522/523
527/526

1966

DIETZEN NO. 385-6

New Bearing Tree.

19" D. Fir Scribed T315 R4W S 578 E 96° CS RT

32" Fir Stamp Scribed T315 R4W S 162W 58° CS RT

Scribed T315 R4W S CS RT

2-11-66

(Renewed H)

X 2/12

C.S. No. 54/20-12