

Renewal

S29/S28
S32/S33

T315 RAW

Found:

Iron Pipe at Sec cor

16" Fir Now 16" N 15° E 22' ¹
Shows good Scar

18" Fir Now 18" N 42° N 6' ²
Scribe visible "T315 RAW"

18" Fir Now a stump S 50° W 13' ³

40" Fir Now 40" S 13° E 32' ⁴
Shows good Scar

Renewed:

Set Brass cap at Sec cor MKD,
County Surveyors Office

T315 RAW

S29/S28
S32/S33

1966

DIETZGEN NO. 385-6

New Bearing Tree

13" D. Fir S 66° W 10' ²
Scribe d: T315 RAW S 32° 45' BT

Renewal #17

2-11-66
~~CS~~
S 32°

*115

C. S. File No. 54/20-15