

Renewal Fee Loc. $\begin{matrix} S6 \\ 51 \\ 57 \\ 512 \end{matrix}$ T31S R4+5W

Found:

32" Fir Now 36" S 13W 72° E

opened tree for scribe "BT"

12" Laurel N 13W No trace of this tree,

Renewed.

Set Brass cap at Sec, cor. MKD

County Surveyors office

T31S
 $\begin{matrix} R & & R \\ S & 51 & 57 \\ W & 512 & W \end{matrix}$
 1966

New Bearing Trees:

8" D. Fir S 12 $\frac{1}{2}$ W 90°
 Scribed, T31S R5W S 12 CS BT

12" D. Fir N 50 W 110°
 scribed T31S R5W S 1 CS BT

1-29-66
~~J.W.B.~~
 J.C.B.
~~J.W.B.~~

* #164-4W
 #70-25W

O.K. J.W.B.

U.S. File No. 51/20-52