

Renewed 516 515 7315 RSW

Found

16" D.F.W. Now 38" N40W 4^o
Part scribed "f s" visible
Distance from approx. Fall
No trace of 12" P.F.W. S88E 8^o

Renewed

Set brass cap of $\frac{1}{2}$ cor MKD.
county surveyors office

7315 RSW

$\frac{1}{2}$ 516/515

1966

New Bearing Trees:

12" D.F.W. N66E 22^o
scribed $\frac{1}{2}$ 515 CS RT

Reblazed & Rescribed

38" D.F.W. N40W 4^o
scribed $\frac{1}{2}$ 516 CS RT

$\frac{1}{2}$ cor line about 66^o ft south of
Ravine

6-13-66

~~J. W. B.~~
~~J. W. B.~~
J. W. B.

499V

* OK J.W.B.

C.S. No. 53/25-14

DIETZGEN NO. 3895-6