

Renewal 517/516 T315 R5W

Found:

Fir Post at $\frac{1}{4}$ cor

12" Fir Now 40" S75W 27 $\frac{1}{2}$
opened for old Scribe Marks

Tree had been opened before but
could not see any marks. O.B.T

39" D Fir Now 36" S78E 31 $\frac{1}{2}$
Shows good Face

Renewed:

Set Brass cap at $\frac{1}{4}$ sec. cor NW
County Surveyors office

T315 R5W

$\frac{1}{4}$ 517/516

1966

DIETZGEN NO. 385-6

Reblazed & Rescribed:

40" D. Fir S75W 27 $\frac{1}{2}$
rescribed $\frac{1}{4}$ 517 CS 27 $\frac{1}{2}$

This Tree is Double Fir

Also cor lies in bottom of
Small Ravine.

Renewal # 33

5-23-66

J.M.P.
1966
J.C.B.

*24

OK. J.W.B. C.S. File No. 54/25-18