

Renewal

$\frac{532}{5655}$

T 315 R 5W  
T 325 R 5W

Found:

Iron Pipe and Brass cap at  
sec cor.

Brass cap MARK

U.S. Dept of Interior B- L- M

$\frac{7315}{32}$   
615  
CC  
T 325 R 5W  
1962

30" Fir Now Stump S 39 E 21 0

8" Yew Now Stump S 63 W 25 2

23" Cedar Scribed "CS" S 6 CS 36 0  
BT"

7" Fir Scribed T 315 R 5W S 70 1/2 W 38 5  
BT

New Bearing Tree

12" Hemlock Scribed T 325 R 5W S 78 1/2 E 27 5  
BT

Also the cor of  $\frac{31}{32}$  Bears  
West 119 7

6-3-66

J. C. C.  
J. W. J.

#130-132  
Renewal #114 A

\*#94

C. S. File No. 54/2527

DIETZEN NO. 385-G