

Renew Sec. Cor

$\frac{56}{57} \frac{55}{58}$

T285 R2W

Ed. O.B.T.s 25 follows -

orig 8" now 16" Live oak N. 65° E. 58 ^(slope) ft.

Record. Bearing - N. 60° E. - 2 live shows good cor

orig. 8" now 15" Laurel S, 60° E. 56 ⁸ ft.

2 live - Burned out No scribe Ed.

Record Bearing S. 70° E.

orig. 10" now 17" Laurel S 20° W, 43 ⁶ ft.

2 live - we open & find scribe & Reverse

orig. 7" now 15" Laurel N. 45° W. 46 ² ft.

Record. Bearing N 40° W. - 2 live opened by

Don Wright of U.S. Ply - scribe visible in

very poor cond. at cor point, The

intersection of 3 distances & one

good bearing to S.W. set 1" I.P. &

BRASS COP MKd. "COUNTY SURVEYOR'S

OFFICE 1968 T285 $\frac{56}{57} \frac{55}{58}$ R2W"

& MK. New B.T.s -

6" Live oak S. 33° E. 10 ⁸ ft.

Mkd. "T285 R2W 58 CS BT"

7" Live oak N. 67° W. 45 ⁸ ft.

Mkd. "T285 R2W 56 CS BT"

16" Live oak N. 66° E. 58 ² ft. (slope)

Mkd. "T285 R2W 55 CS BT" (O.B.T.)

18" Laurel S. 32° W. 35 ⁰ ft.

Mkd. "T285 R2W 57 CS BT"

This cor. lies on steep S.W. slope

April 24, 1968

U.P.T.

J.H.

U.P.

R. R. Tracy

C.S. File No. 54/26-9
OK J.W.B.