

Renew  $\frac{1}{4}$   $\frac{528}{533}$  T25S R3W

Fd. G.L.O. BRASS COP. MKD.  $\frac{1}{4}$   $\frac{528}{533}$  1943"

ORIG. 1883 B.T.s NOW STUMP N.E. &

WINDFALL TO S.W. - 1943 RESURVEY

B.T.s as follows -

24" NOW 32" FIR S.  $23\frac{1}{2}^{\circ}$  E. 31' ft.

SHOWS GOOD SCAR - WEDONNOT OPEN.

N.E. B.T. NOW SHATTERED STUMP.

WE MK. NEW B.T.s -

4" D. FIR N.  $3^{\circ}$  W. 4' ft.

MKD.  $\frac{1}{4}$  S CS BT" (ONLY)

6" I. CEDAR S.  $76^{\circ}$  E. 36' ft.

MKD.  $\frac{1}{4}$  S33 CS BT"

THIS COR. LIES ON STEEP W. SLOPE ON E.-W. CUTTING LINE - CUTOFF TO N.

June 30, 1966

U.R.T.

J.B.

J.H.

FILED

RECEIVED

JUN 30 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

K/O.K. J.W.B.

\* 254

C. S. FILE NO.

54/2T<sup>12</sup>