

Renew  $\frac{1}{4}$  522/523 T255 R3W

Ed. GLO. BRASS CAP. MKd.  $\frac{1}{4}$  522/523 1943"

& BT's 28 Recorded in Rev. #18 as follows

BURNED 48" FIR SNAG S. 86° W. 27  $\frac{1}{2}$  FT.

scribe visible - This is 1943 Resurvey BT.

18" Hemlock S. 82° E. 49° FT.

scribed.  $\frac{1}{4}$  523 CS BT" - Now STUMP.

48" FIR N. 24° W. 4  $\frac{1}{2}$  FT.

scribed  $\frac{1}{4}$  522 CS BT" - Now STUMP.

we MK. New BT's -

6" D. FIR N. 53° E. 50  $\frac{2}{2}$  FT.

Mkd.  $\frac{1}{4}$  5 CS BT"

5" D. FIR S. 68° W. 39  $\frac{8}{8}$  FT.

Mkd.  $\frac{1}{4}$  5 CS BT"

Steel fence post along side

BRASS CAP. COR. of TIMBER BEARS

South approx. 200 FT.

July 6, 1966

V.R.T.

J.B.

J.H.

FILED

RECEIVED

JUL 5 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

W.A.K.

\*#60 J. W. B.

C. S. File No. 57/27-17