

Renew $\frac{1}{4}$ $\frac{517}{520}$ T255 R3W

Ed. G.L.O. BRASS CAP MKD. " $\frac{1}{4}$ $\frac{517}{520}$ 1944"

1944 Resurvey BT's as follows -

14" Now 20" FIR N. $87\frac{1}{2}^{\circ}$ W. 70' ft.

2 live - good cond. - Shows very good scar
we do not open -

38" Now 40" FIR S. 72° W. 34' ³ ft.

Now turned out stump showing healed
Blaze on bottom side.

MARK NEW BT'S -

11" D. FIR S. 28° E. 36' ⁵ ft.

Mkd. " $\frac{1}{4}$ 520 CS BT"

6" D. FIR N. 55° E. 23' ¹ ft.

Mkd. " $\frac{1}{4}$ 517 CS BT"

This cor lies on Rolling top
of spur sloping N.W. also find
Steel fence post set along side
BRASS CAP.

July 14, 1966

FILED
RECEIVED

U. R. T.
J. H.

JUL 13 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

* #65
D. K. J. W. B.

C. S. File No.

57/27-22