

Renew $\frac{1}{4}$ $\frac{519}{530}$ T255 R3W

Fd. B.T.s marked in 1944 Resurvey
25 follows -

14" Now 20" Hemlock N. 22° E. 51 $\frac{5}{2}$ ft.
Shows " $\frac{1}{4}$ 519 BT" on partially healed
Blaze - alive & in good cond.

8" Now 11" Fir S. 51° W. 11 $\frac{2}{2}$ ft.
Healed blaze - chopped out - scribe mks.
Visible on pitched face, alive

We find no trace of Brass cap called
for. Set 1" I.P. & Brass cap MKd.

"COUNTY SURVEYOR'S OFFICE 1966

T255 $\frac{1}{4}$ $\frac{519}{530}$ R3W " & 1/4 New BT -

16" D. Fir S. 12° W. 19 $\frac{8}{2}$ ft.

Mkd. " $\frac{1}{4}$ 530 CS BT"

BRASS CAP LIES 1 FT. N. & 2 FT.

W. OF EAST END OF 54" CORRUGATED
STEEL CULVERT UNDER NEW GRASSY
CREEK ACCESS ROAD. COURSE E. CURVING
TO S.W.

FILED

RECEIVED

U.P.T.

JUL 13 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C.S. File No. 57/27-24

G.W. J.W.B

*67