

515/514

Renew Sec. Cor 522/523 T255 R3W

Ed. G.L.O. BRASS Cap MKd "T255 R3W

515/514
522/523 1943 " & ORIG. 1583 B.T's

25 follows -

12" Now 16" FIR N. 35° E. 27 1/2 ft.
previously opened & shows - "T255 R 5"
scribe - now Dead snag.

20" Now 27" FIR S. 35° E. 19 3/4 ft.
Now 5 Tump. - shows scar.

32" Now 48" FIR S. 64° W. 9 3/4 ft.

2 live - shows good scar - we do not open.

ORIG. N.W. B.T. Now gone. & 1943
Resurvey B.T. to NW. Now Turned out
stump, we mk. New B.T.s -

7" Hemlock N. 36° E. 5 5/8 ft.

Mkd. "T255 R3W 514 CS BT"

16" Hemlock N. 70° W. 47 5/8 ft.

Mkd. "T255 R3W 515 CS BT"

8" Hemlock S. 4° E. 21 7/8 ft.

Mkd. "T255 R3W 523 CS BT"

Also find steel fence post set
along side BRASS cap.

July 25, 1966

V.R.T.
J.B.
J.H.

~~W.R. Peace~~
* o.w. J.W.B.

C.S. File No. 54/27-54