

Renew $\frac{1}{4}$ 519 + 520 T255 R3w

Fd. GLO. Brass cap MKd. " $\frac{1}{4}$ 519/52 1944"

\$ Stumps of BTs as Recorded in Pen. #28

as follows -

14" Fir Stump N. 80° E. 31² Ft.

Rotting Badly - Fragmentary scribe visible

34" Fir Stump S. 77° W. 165 Ft.

" $\frac{1}{4}$ 519 CS BT" scribe visible.

42" Fir Stump N. 26° E. 39⁰ Ft.

" $\frac{1}{4}$ 520 CS BT" scribe visible - Beginning

To Rot. we MK. New BTs -

4" D. Fir S. 68° W. 11¹ Ft.

Mkd. " $\frac{1}{4}$ 519 CS BT"

4" D. Fir S. $53\frac{1}{2}^{\circ}$ E. 89² Ft.

Mkd. " $\frac{1}{4}$ 520 CS BT"

This cor. Lies in N.-S. fence.

Sept 2, 1966

V.R.T.
J.B.
J.H.

(Handwritten signature)
FILED
RECEIVED

SEP 2 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#122

C.S. No. 54/27 -66